

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
1	SU-YAPI Eng. Cons. Co.	1999	Highway Bridges	İzmir Bergama	Geotechnical Report and Design	The geotechnical report on the foundations of six bridges and pile/raft design
2	ALAÇATI Tourism Invest. Co.	1999	Housing Complex	İzmir Alaçatı	Geotechnical Report	An evaluation about the retaining structures
3	ESER Cons. Eng. Co.	1999	Railway	İzmir Menemen	Geotechnical Report	The design of cut sections in Menemen-İliç Railway Project
4	ESER Cons. Eng. Co.	1999	Highway	Adapazarı Kandıra	Highway Geotechnical Report	The geotechnical report of Adapazarı-Kandıra Highway
5	MEKAN Map Construction Eng. Co.	1999	Highway	Kocaeli Kandıra	Highway Geotechnical Report	The geotechnical report of Kandıra Karasu Highway
6	ERA Geologic Serv. Co	1999	Motorway	Aydın Denizli	Motorway Geotechnical Report	The geotechnical report of Aydın Denizli Motorway
7	ETAP Const. Eng. Co.	1999	Highway	İzmit Yalova	Highway Geotechnical Report	The geotechnical report of İzmit Yalova Highway
8	FKM Consulting and Engineering Co.	1999	Highway	Eskişehir Bilecik	Highway Geotechnical Report	The geotechnical report of Bilecik-Bozüyük Highway
9	ERKA-AS Co.	1999	Railway	Bandırma Bursa	Railway Geotechnical Report	Geotechnical report of the Bandırma Bursa Railway Project
10	YÜKSEL-ENER Partnership	2000	Wastewater Treatment	Adana	Geotechnical Report	A report on the foundations of Digesters in Adana West Waste Water Treatment Plant
11	ESER Cons. Eng. Co.	2000	Highway	Amasya	Highway Geotechnical Report	Geotechnical Report of the Amasya Highway
12	ALTYAPI Eng. Co.	2000	Highway	Sinop	Highway Geotechnical Report	The geotechnical report of Sinop-Erfelek Highway
13	Makina Kimya Endüstrisi Kurumu	2001	Industrial Plant	Ankara	Geotechnical Report	The soil investigation report for the Units of Explosive Production Factory

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
14	YÜKSEL Construction Co.	2001	Power Plant	Ankara	Geotechnical Report and Design	The geotechnical report of ANKARA CCPP Plant Area
15	MESA Mass Housing Investment Inc.	2001	Housing Project	Ankara	Geotechnical Report	The Geotechnical Report for three 28 story residence buildings
16	ESER Cons. Eng. Co.	2001	Highway	Ankara	Highway Geotechnical Report	The geotechnical report for Çatalzeytin-Ayancık Highway.
17	ŞEREFİOĞLU Const.Trade Co.	2001	Highway	Kocaeli Yalova	Highway Geotechnical Report	The Geotechnical Report for the access highway to Earthquake Houses in Gündoğdu-Yalova
18	GEZER Industry Construction Trade Co.	2002	Water Treatment	Ankara	Geotechnical Report	The geotechnical report of ANKARA CCPP Water Treatment Area
19	GÜRİŞ Construction Co.	2002	Pump Station	Sapanca	Geotechnical Report	Geotechnical report for the Tüpraş-Sapanca Water Pumping Station
20	SÖNMEZ-VONA Joint Venture	2003	Factory	Ankara	Geotechnical Report	The geotechnical report for a Serum Factory in Akyurt Ankara
21	ŞEREFİOĞLU Const.Trade Co.	2003	Highway	Kocaeli Yalova	Highway Geotechnical Report	The Geotechnical Report for the access to Earthquake Houses in Karamürsel-Yalova
22	ALKATAŞ Co.	2004	Wastewater Treatment	Bursa	Geotechnical Report and Design	The geotechnical report and foundation design of Bursa Demirtaş Industrial Area Water Treatment Plant
23	VATECH Hydro Gmbh.	2004	Power Plant	Romania	Geotechnical Report and Design	Bucharest Power Plant Geotechnical report
24	ALKE-İLKUMUT Jv.	2004	Industrial Park	Romania	Geotechnical Report	Geotechnical report about the settlements in the fill for Braila Industrial Park
25	PİRAMİT Const. Co. Inc	2004	Factory	Gebze	Geotechnical Report	The Geotechnical Report for the Plaster Factory of LAFARGE- DALSAN
26	ESPM Project and Engineering Co.	2004	Railway	Konya	Geotechnical Report and Design	The geotechnical report for the Yenişehir Street Railway Underpass

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
27	Mr. Kenan KARABACAK	2004	Factory	Karabük	Geotechnical Report	The geotechnical report for a steel factory extension
28	S.S TEDKENT Cooperative	2005	Housing Complex	İstanbul	Geotechnical Report	The geotechnical report for a housing project in İstanbul
29	OHL-ALARKO Joint Venture	2004 2005	Ankara-İstanbul Railway Rehabilitation Project	Ankara	Railway Geotechnical Design	The design of foundations for 12 river bridges, 4 viaducts 32 underpasses, 25 overpasses and geotechnical report for the alignment
30	YENİ GİMAT İşyerleri Co.	2005	Shopping Mall	Ankara	Geotechnical Report and Design	The design of foundations for ANKA Mall Shopping Center.
31	TET Architecture Eng. Cons. Trade Ltd. Co.	2005	Power Plant	İzmir	Geotechnical Report and Design	The geotechnical report and foundation design of İzmir Kemalpaşa Combined Cycle Power Plant
32	BARES Power Prod. Trade Co.	2005	Wind Farm	Bandırma	Geotechnical Report	The geotechnical report and Site Investigation for the Wind Power Plant in Bandırma
33	JEMAS-SU Eng. Ltd.	2005	Bridge	İzmit	Geotechnical Report and Design	The design of foundations for the İzmit Periphery Road Bridge
34	ŞEREF OĞLU Const.Trade Co.	2005	Highway	İzmit	Geotechnical Report	Geotechnical Report of the Connection Road of Kocaeli-Yalova Earthquake Apartment Buildings
35	ALKE-İLKUMUT Srl. Jv.	2006	Industrial Park	Romania	Geotechnical Report	Geotechnical Report for the Expected Completion time for the settlements of Braila Industrial Park
36	MESA Mass Housing Investment Inc.	2006	Housing Complex	Ankara	Geotechnical Report and Design	The geotechnical report and foundation design of TOKİ Highrise buildings located in Çayyolu-Ankara
37	FERNAS Plaster Industry Trade Co.	2006	Factory	Ankara	Geotechnical Report	The site investigation and Geotechnical report for the Plaster Factory in Gölbaşı-Ankara
38	GÜLERMAK-DOĞUŞ Joint Venture	2006	Railway	İstanbul	Geotechnical Report and Design	The geotechnical report for the Olympic Stadium Train Park Area of the Otogar-Bağcılar Light Rail System
39	YILDIZ-DOĞAN Construction Trade Co.	2006	Culture Centre	Sivas	Geotechnical Report and Design	The design of Foundations and preloading Project for the structures to be built at the Sivas Congress and Culture Center

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
40	FERNAS Plaster Industry Trade Co.	2006	Gypsum Plant	Çanakkale	Geotechnical Report	The site investigation and Geotechnical report for the Gypsum Plant in Çan-Çanakkale
41	CENGİZ-MAPA-MAKYOL	2006	Bridge	Ardeşen	Geotechnical Report	The geotechnical report for the approach embankments of Ardeşen Port Bridge
42	Nur Construction Co.	2006	Irrigation Channel	Konya	Geotechnical Report and Design	The geotechnical report for 20m long water channel and the design of drainage system for the construction of the channel under groundwater table.
43	SİGMA Construction and Tourism Management Trade Co.	2006	High Speed Railway	Ankara Eskişehir	Geotechnical Report and Design	Design of railway cuts and remedial measures for the railroad embankment on soft soils
44	MİMPAŞ Engineering Co.	2006	Pump Station	Mürselli	Geotechnical Report and Design	The geotechnical report of the Mürselli Pump Station to be construction in the irrigation project of Aydın Plain
45	GAMA Power Systems Co. Inc.	2007	Power Plant	Pakistan	Geotechnical Report and Design	The geotechnical report of the Mobile Power Plant to be constructed in Pasrur-Sialkot Pakistan
46	Coyne and Bellier Engineering and Consulting Ltd. Co.	2007	Power Plant	Fethiye	Geotechnical Report and Design	The geotechnical report for the weir, channels, tunnel and pump station of Eşen-II hydro power plant
47	Ambassader de France	2007	Highschool	Ankara	Geotechnical Inv. And Report	The geotechnical investigations and geotechnical report of the Charles de Gaul İncek Lycee
48	ESER Cons. Eng. Co.	2007	Highway	Beyşehir	Geotechnical Report	The geotechnical report for the Beyşehir-Yenişarbademli Highway Project
49	GÜNSAYIL Cons. Trade and Industry Ltd.Co.	2007	Gas Pipeline	İstanbul	Geotechnical Report	The geotechnical report for the underpass of the natural gas pipeline below Ankara-İstanbul Motorway
50	GÜLERMAK-DOĞUŞ Joint Venture	2007	Underground	İstanbul	Geotechnical Report	The geotechnical parameter report for the design of the tunnels of Otogar-Bağcılar metro line
51	MEDVIEW Sunset Ltd.	2007	Hotel Complex	Cyprus	Geotechnical Report	The geotechnical report for the Hotel Project in Girne-Lapta
52	MÖN Construction and Trade Ltd. Co.	2007	Interchange	Eskişehir Bilecik	Geotechnical Report	The geotechnical report for the Railway displacement at Bursa Interchange of Bozüyük-Mekece Highway

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
53	ÖNCÜOĞLU Architecture Planning	2007	Shopping Mall	Russia	Geotechnical Report	Geotechnical report on the foundations of shopping mall in Ustkamenegorsk
54	EMİ-ÖZBEK-DEVİRAN Joint Venture	2007	Highway	Çorum	Geotechnical Report	The geotechnical report for the Osmançık-Gümüşhacıköy Highway Project
55	MİMPAŞ Engineering Co.	2007	Dam	Uşak	Geotechnical Report and Design	The geotechnical report and design of Uşak-Sivaslı Dam (50m high).
56	MNG Zentaş Co.	2007	Highway	Adapazarı	Geotechnical Design	The design of various structures such as nailed walls, piled cantilever retaining walls near Sakarya River for the widening of Mekece-Adapazarı Highway
57	MESA Mass Housing Investment Inc.	2007	Housing	Ankara	Geotechnical Report and Design	The geotechnical assessment and determination of the foundation type of 7 multistorey (16-18storeys) buildings in Megatürk Project
58	KGM Turkish General Directorate of Highways	2007	Viaduct	Adana	Geotechnical Design	The geotechnical design of the piled foundations of Seyhan Viaduct.
59	ERKA-AS Co.	2008	Dam	Bodrum	Geotechnical Design	The geotechnical design of the dam body of Varvil-1 pond
60	ESER Cons. Eng. Co.	2008	Embassy Building	Ankara	Geotechnical Report	The geotechnical Report for the Canada Embassy building
61	CIMPOR YIBITAS Cement A.Ş	2008	Industrial Plant	Ankara	Geotechnical Report and Design	The geotechnical report for the Ankara-Hasanoğlan Cement Factory
62	ONUR Construction and Trade Co.	2008	High Speed Railway	Konya	Geotechnical Report	The geotechnical report for the measures to be taken for the carstic cavities under the track
63	ESER Cons. Eng. Co.	2008	Highway	Elazığ	Geotechnical Report	The geotechnical report for the Elazığ-9. Bölge Hududu Highway Project
64	GAMA Power Systems Co. Inc.	2008	Power Plant	Russia	Geotechnical Report	The geotechnical report of the Surgut State PGU-400x2 Power Plant.
65	A TEC Power Plant Systems A.G	2008	Power Plant	Turkey	Geotechnical Report	The geotechnical report of the Bandırma CCPP.