

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
1	JMS Co. Ltd.	1999	Highway	Sinop	Landslide Stabilization	An investigation report on the landslide in Ayancık-Sinop highway was prepared. The report consisted of the mechanism of lanslide, soil conditions and instrumentation
2	Middle East Technical University	1999	Dormitory Building	Rize	Landslide Stabilization	The design of a bored piled wall to stabilize a landslide occured in a dormitory building under construction in Rize
3	Middle East Technical University	2000	Hospital Building	Rize	Landslide Stabilization	The design of a piled retaining wall
4	ARK Const. Engineering Consulting Co.	2000	Highway	Isparta	Landslide Stabilization	An anchored pile wall structure and rockfill was designed for the stabilization of a landslide occured in Isparta Antalya Highway
5	AKYAPI Const. Co.	2000	Landslide Stabilization	İzmit Dilovası	Landslide Stabilization	An anchored pile wall structure, drainage system and rockfill was designed for the stabilization of a landslide occured in İstanbul Ankara Highway
6	TÜRKERLER-GÜRİŞ Joint Venture	2003	Water Treatment	İstanbul	Landslide Stabilization	Consulting for lanslide rehabilitation project with large diameter piles for İSKİ Taşoluk water treatment plant
7	TETA Construction Co.	2003	Bridge	İstanbul	Landslide Stabilization	The stabilization of FSM Bridge North approach embankment with large diameter piles and permanent anchors
8	SEDAŞ-ULUOVA Joint Venture	2005	Housing Complex	İstanbul	Landslide Stabilization	The stabilization of a lanslide in Ortaköy Valley by large diameter bored piles
9	S.S Doğakent Cooperative	2006	Housing Complex	Ordu	Landslide Stabilization	The landslide rehabilitation and drainage project for a big landslide covering 10 storey buildings located on a steep hill
10	MAPA-AREVA Joint Venture	2008	Transformer	İstanbul	Landslide Stabilization	The rehabilitation project for the mass landslide experienced in the cuts of Melen Transformer