

NO	COMPANY	YEAR	TYPE OF STRUCTURE	LOCATION	JOB TYPE	JOB-DETAILS
1	Ministry of Public Works and Settlement	1998	Headquater Building	Ankara Bakanlıklar	Soil Investigation Report	Cost Guard Headquarter Building
2	Ministry of Public Works and Settlement	1998	Hospital Building	Ankara	Soil Investigation Report	The soil investiation report of Ankara Traffic Hospital with 400 bed capacity
3	Ministry of Public Works and Settlement	1998	Hospital Building	Tekirdağ	Soil Investigation Report	The soil investiation Report of Tekirdağ Government Hospital with 250 bed capacity
4	CBO Construction Co.	1998	School Building	Muş Kızılağaç	Soil Investigation Report	The soil investigation report of a school building
5	CBO Construction Co.	1998	School Building	Muş Sütluce	Soil Investigation Report	The soil investigation report of a school building
6	CBO Construction Co.	1998	School Building	Muş Selçuklu	Soil Investigation Report	The soil investigation report of a school building
7	CBO Construction Co.	1998	School Building	Muş Rüstemgedik	Soil Investigation Report	The soil investigation report of a school building
8	Ministry of Public Works and Settlement	1998	Hospital Building	Samsun	Soil Investigation Report	The soil investiation report of Samsun Hospital with 100 bed capacity
9	ANKARA Sincan Municipality	1999	Interchange	Ankara Sincan	Soil Investigation Report	Geotechnical report of the Sincan-Atatürk street Interchange
10	Ministry of Public Works and Settlement	1999	Dormitory Building	Ankara Cebeci	Soil Investigation Report	Ankara Dormitory (400 Student Capacity) soil investigation report
11	Turkish Chamber of Cement Manufacturers	1999	Office Building	Ankara Akyurt	Soil Investigation Report	The soil investigation report for the office building and social facilities complex
12	SONAR Drilling Co.	1999	Office Building	Ankara Anittepe	Soil Investigation Report	The soil investigation report for a hotel building
13	OYAK Const. Co.	1999	Housing Complex	Ankara Eryaman	Soil Investigation Report	The soil investigation report of a mass housing project area located in Eryaman Ankara
14	M.Can SEMİZ	2000	Military Headquarter Building	Samsun	Soil Investigation Report	The geotechnical report of a military headquarter building located in Samsun